

SEASTAR™ BASELINE® BROMINE

Product Code	S021201-SSNP01
Analyte	Trace Impurities in ppt (pg/g)
Aluminum (Al)	100
Antimony (Sb)	100
Barium (Ba)	10
Beryllium (Be)	10
Bismuth (Bi)	10
Boron (B)	Information Only
Cadmium (Cd)	10
Calcium (Ca)	100
Cerium (Ce)	10
Cesium (Cs)	10
Chromium (Cr)	50
Cobalt (Co)	50
Copper (Cu)	50
Dysprosium (Dy)	10
Erbium (Er)	10
Europium (Eu)	10
Gadolinium (Gd)	10
Gallium (Ga)	50
Hafnium (Hf)	10
Holmium (Ho)	10
Indium (In)	10
Iron (Fe)	100
Lanthanum (La)	10
Lead (Pb)	10
Lithium (Li)	50
Lutetium (Lu)	10
Magnesium (Mg)	100
Manganese (Mn)	50
Molybdenum (Mo)	100
Neodymium (Nd)	10
Nickel (Ni)	100
Niobium (Nb)	Information Only
Palladium (Pd)	Information Only
Platinum (Pt)	Information Only
Potassium (K)	500
Praseodymium (Pr)	10
Rhenium (Re)	50
Rhodium (Rh)	Information Only
Rubidium (Rb)	50
Ruthenium (Ru)	50
Samarium (Sm)	10
Scandium (Sc)	50
Sodium (Na)	100
Strontium (Sr)	50
Tellurium (Te)	10
Terbium (Tb)	10
Thallium (Tl)	Information Only
Thorium (Th)	Information Only
Thulium (Tm)	10
Tin (Sn)	100
Titanium (Ti)	100
Tungsten (W)	Information Only
Uranium (U)	10
Vanadium (V)	50
Ytterbium (Yb)	10
Yttrium (Y)	10
Zinc (Zn)	100
Zirconium (Zr)	10